

## Olga Holguin

---

**From:** online-bounces@nmsu.edu on behalf of Eunice Martinez Campos <eunice7@ad.nmsu.edu>  
**Sent:** Wednesday, February 17, 2016 8:41 AM  
**To:** Annette McConnell; Webster, Jon  
**Cc:** Outage@nmsu.edu  
**Subject:** [Online] [Outage] Outage Notification: 02/17/2016

### OUTAGE NOTIFICATION:

**To:** Annette McConnell, Stucky Hall  
**From:** Fernando Ortega, Facilities and Services  
**Outage Type:** Sanitary Sewer/ Partial Building Utility Service Outage

---

**Date of Outage:** February 17, 2016

**Time of Outage:** 7:00 am

**End Date of Outage:** February 17, 2016

**End of time Outage:** 5:00 pm

**WO#:** 16-025189

**Location:** Stucky Hall

**Note:** This confirms arrangements by: Fernando Ortega, Facilities and Services

**What is the purpose of the outage:** The purpose of the outage is to replace a section of the sewer drain that has failed. Excavating, barricading and pipe replacement will be taking place. The drain outage is necessary to make the repairs that are needed to have a properly functional sewer system.

**What buildings will be affected and how will they be affected:** Stucky Hall and NMDA will be the two buildings affected. NMDA (New Mexico Department of Agriculture) will have one restroom out of order. The restroom is located in the petroleum lab. Stucky Hall will be fully affected. All restrooms and drains will be out of service.

**What impact will this outage have on the systems/users:** Stucky Hall's building occupants will have to use the restroom located at NMDA.

**What if any, measures are being taken to minimize the impact on users:** This outage was coordinated with Annette McConnell and Jon Webster.

**If you have any questions please contact: Fernando Ortega, Facilities and Services, 646-4604**

## Eunice Martinez Campos

---

**From:** Eunice Martinez Campos  
**Sent:** Monday, February 22, 2016 1:57 PM  
**To:** bdmon@nmsu.edu  
**Cc:** Glen Haubold; Timothy Dobson; Olga Holguin  
**Subject:** Building Monitor List

**Importance:** High

Good afternoon everyone,

It is that time to ensure the Building Monitors list is up to date. Please let me know via email if there are any discrepancies or changes to be made.

You can find the list at <http://facilities.nmsu.edu> under the “Customers” tab.

Thank you.

Eunice Martinez  
Student Assistant- Administration  
Facilities and Services Department  
New Mexico State University  
[eunice7@nmsu.edu](mailto:eunice7@nmsu.edu)  
(575) 646-2101